





Certified Inspection Report for:		Contact:	Order No:	Site Address:	SHEET			
Woodmansey Parish Council Juniper Cottages, 1 Manor Barn, Millington York YO42 1TX		Judith Roberts Tel: 01759 307 423 / 07825 791 790 Email: woodmanseyclerk@lawks.co.uk	332208	King Street, Woodmansey HU17 0TE	1 of 3			
DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL
Jill Climber - Yellow on Black Wetpour	Wicksteed	L	Paint is wearing. Recommend this item is rubbed down and repainted. Note that BS EN 1176:2008 states that paint shall be non-toxic. Suitable paint (primer and top coat) is available from Wicksteed Sales Dept at a cost of £20 per litre.					
RP 182 2.4m 1 Bay Swing 2 x Cradle Seats on Black Wetpour	Record 1995		Generally satisfactory, but the swing frame would benefit from repainting (red)					
Free Standing Slide on Black Wetpour	Record	L	Monitor gaps at the edge of the wetpour playing surface for trip hazards.					
Whale Spring Mobile - Blue on Black Wetpour	Ledon	L	Recommend the damaged plastic cover at the base of the spring is replaced.	1	B610SPEC	SPRX2 Ledon Base Plate Covers (Pair)	£53.21	£53.21
		L	Monitor minor damage to the handrail for sharp edges etc.	2	B610SPEC	F194 M6 x 16mm S/S Hex Head Bolt	£0.17	£0.34
		L	Monitor minor corrosion on the spring.	2	B610SPEC	F135 M6 S/S Nylock Nut Delivery from Playdale	£0.08 £7.50	£0.16 £7.50
Elephant Spring Mobile - Yellow Model 414 on Black Wetpour	Ledon 2007	L	Monitor minor damage to the footrests and hand holds.			<b>Labour to replace parts*</b> (This is based on the work being ordered at the same time as the work at Southwood Park)		
2.4m 1 Bay Swing 2 x Flat Seats on Black Wetpour	Record		Satisfactory condition.			Playdale advise that parts prices are valid for 1 month		
Storm Multiplay Unit with Curved Slide Chute on Black Wetpour	Wicksteed	L	Paint is wearing, in particular at access and climbing areas. Recommend affected areas are rubbed down and repainted. Note that BS EN 1176:2008 states that paint shall be non-toxic. Suitable paint (primer and top coat) is available from Wicksteed Sales Dept at a cost of £20 per litre.			Continues on next sheet...		
 Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028		H/MH M V/L	<b>INDICATION OF RISK RATING ASSESSMENT</b> HIGH & MEDIUM HIGH RISK - See Introductory Notes MEDIUM RISK - See Introductory Notes VERY LOW & LOW RISK - See Introductory Notes	INSPECTED BY :- <b>A J Hayes</b> DATE :- <b>09. 11. 2017</b>	PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. LABOUR TO FIT PARTS * Based on all works ordered	(E&O.E.)	£61.21 £0.00 £61.21	See sheet 3

Certified Inspection Report for:		Contact:	Order No:	Site Address:	SHEET				
Woodmansey Parish Council Juniper Cottages, 1 Manor Barn, Millington York YO42 1TX		Judith Roberts Tel: 01759 307 423 / 07825 791 790 Email: woodmanseyclerk@lawks.co.uk	332208	King Street, Woodmansey HU17 0TE	2 of 3				
DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL	
Agility Unit with Grey Posts on Black Wetpour	unknown	L	Monitor wear on the paintwork. Fails BS EN 1176 Head & Torso Probe Test at 1 opening in the blue frame (Ref BS EN 1176:2008 Part 1 Section 4.2.7.2) No remedial action is feasible at present.						
Free Standing Basketball Goal on Concrete	Parkdale PPL	L	Monitor cracks in the concrete surface for trip hazards.						
2 x Football goals on Grass	unknown	L	Generally satisfactory, but recommend grounds maintenance as required to reduce hazards at areas of ground erosion.						
Perforated Metal Seats	Record	L	Generally satisfactory, but the seat near the unit with silver posts would benefit from rubbing down and repainting (corrosion)						
Litter Bins	unknown		Satisfactory condition.						
2 x Timber Seats	unknown	L	Generally satisfactory, but the raised edges of the concrete slabs may create trip hazards. Recommend grounds maintenance as required.						
Metal Bow Top Fence	unknown		Satisfactory condition, but fails BS EN 1176 Head & Neck Probe Test, Ref BS EN 1176:2008 Part 1 Section 4.2.7.2. No action recommended at present.						
Pedestrian Gates	unknown	L	Generally satisfactory, but monitor for potential pinch hazards (minimum 12mm gap recommended, ref BS EN 1176:2008 Part 1, section 4.2.7.6) Recommend grounds maintenance as required to reduce trip hazards at areas of ground erosion, exposed concrete and metal ground strips.						
			Continues on next sheet...						
  Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028			<b>INDICATION OF RISK RATING ASSESSMENT</b> HIGH & MEDIUM HIGH RISK - See Introductory Notes MEDIUM RISK - See Introductory Notes VERY LOW & LOW RISK - See Introductory Notes		INSPECTED BY :- <b>A J Hayes</b> DATE :- <b>09. 11. 2017</b>		PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. LABOUR TO FIT PARTS * Based on all works ordered		<b>£0.00</b> <b>£61.21</b> <b>£61.21</b> <b>See sheet 3</b>

<b>Certified Inspection Report for:</b> Woodmansey Parish Council Juniper Cottages, 1 Manor Barrn, Millington York YO42 1TX		<b>Contact:</b> Judith Roberts Tel: 01759 307 423 / 07825 791 790 Email: woodmanseyclerk@lawks.co.uk		<b>Order No:</b> 332208		<b>Site Address:</b> King Street, Woodmansey HU17 0TE		<b>SHEET</b> 3 of 3				
DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL				
<b>Vehicle Access Gate</b>  <b>General</b>		<b>M</b>  <b>L</b>  <b>L</b>	Satisfactory condition (Locked at the time of inspection)  Access by dogs is not physically prevented and routine inspection should include monitoring and removal of animal faeces. (Litter (animal droppings) order 1991 of The Environment Protection Act 1990 requires public walks and pleasure grounds to be free from animal faeces) Recommend moss growth is removed from the wepouir playing surfaces to reduce slip / trip hazards. Best method is to pressure wash with a mild detergent solution. The provision of a sign (pictogram) is recommended giving the following information: a) General emergency telephone number (999 or 112) b) Telephone number to contact maintenance personnel c) Name of the playground d) Address of the playground e) Other relevant local information, if applicable (ref: BS EN 1176-7:2008 clause 8.2.4)									
<b>WICKSTEED</b> playgrounds  Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028 <a href="http://www.wicksteed.co.uk">www.wicksteed.co.uk</a>			<b>rpil</b> RISK RATING H/MH M V/L		<b>INDICATION OF RISK RATING ASSESSMENT</b> HIGH & MEDIUM HIGH RISK - See Introductory Notes MEDIUM RISK - See Introductory Notes VERY LOW & LOW RISK - See Introductory Notes		<b>INSPECTED BY :-</b> <b>A J Hayes</b> DATE :- <b>09. 11. 2017</b>		<b>PARTS SUB TOTAL</b> BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. LABOUR TO FIT PARTS * Based on all works ordered TOTAL COST OF WORKS, EXC VAT		<b>£0.00</b> <b>£61.21</b> <b>£61.21</b> <b>£180.00</b> <b>£241.21</b>	
		