

Playground Repairs

Report to Woodmansey Parish Council

15th February 2016

1. Introduction

The annual inspection a the playground highlighted a number of problems that need resolving. The details plus some indicative costing are listed below.

2 Repairs

Item	Indicative Pricing	Contractor
Minor maintenance, greasing , tightening bolts, replacing covers etc, removing sign posts.	£200	C Beal
Jet washing surfaces at King Street	£350	C Beal
Removing trip hazard at King Street and preparing surface	£100	C Beal
Perimeter repairs at King Street	£1000	Wicksteed
Perimeter repairs at Southwood Park	£6700	Wicksteed
Replacement Cradle two swings @ 125 each*	£250	Wicksteed
4 Dog grids @ £400 each*	£1600	Wicksteed
3 new signs (Two at King Street & 1 at Southwood Park) @ £260 each*	£780	Wicksteed
Totals	£10,980	

* there will be additional costs for fitting

3. Decision Required

- 3.1 To agree some repairs will be undertaken within the next month or so.
- 3.2 To agree on a budget and priority list of repairs
- 3.3 To determine which repairs the council will require multiple quotes before deciding on a contractor.

Judith Roberts
Clerk to the Council
15th February 2016