


PLAY AREA/LOCATION:	DATE:
King St	18/4/2018

INSPECTING ENGINEER:	SIGNED:
Carole Curran	

DEFECT CODE				
D = Requires Urgent Attention				
C = Requires Attention				
B = To Be Kept Under Observation				
/ = Servicable				

ITEM	CODE	Required Action	Date Completed	Completed By
SURFACING				
Surface Contamination	/			
Surface Compaction	/			
Surface Depth	/			
Surface Material Contamination (Soil etc)	/			
Pooling Water	/			
Exposed Footings	/			
PERFORMANCE				
Entanglement Hazzards	/			
Head/Neck Entrapment Hazzards	/			
Looping Hazzards	/			
Protrusion Hazzards	/			
Sharp Points and Edges	/			
Pooling Water	/			
MAINTENANCE				
Tilting and Frost Heave	/			
Chain Wear	/			
Tangled Chains	/			
Cracked and Worn Swing Seats	/			
Bearing Wear	/			
Lubrication	/			
Loose/worn/missing Fasteners	/			
Wood Spliners/Cracking	/			
Broken/Damaged or Missing Parts	/			
Finish/Paint and Rust	/			
SITE				
Fencing	/			
Lighting	/			
Signs	/			
Furniture	/			
Pathways	/			
Pests/Insestations	/			
Waste Bins	/			
General Housekeeping	/			

NOTES:				
NO DEFECTS. 😊				

PLEASE USE REVERSE OF SHEET FOR FURTHER INFORMATION/DETAILS