

<b>PLAY AREA/LOCATION:</b> King Street	<b>DATE:</b> 25 March 2018
---	-------------------------------

<b>INSPECTING ENGINEER:</b> C. Gilmore	<b>SIGNED:</b> 
---	--------------------

<b>DEFECT CODE</b>				
D = Requires Urgent Attention				
C = Requires Attention				
B = To Be Kept Under Observation				
/ = Servicable				

ITEM	CODE	Required Action	Date Completed	Completed By
<b>SURFACING</b>				
Surface Contamination	✓			
Surface Compaction	✓			
Surface Depth	✓			
Surface Material Contamination (Soil etc)	✓			
Pooling Water	✓			
Exposed Footings	✓			
<b>PERFORMANCE</b>				
Entanglement Hazards	✓			
Head/Neck Entrapment Hazards	✓			
Looping Hazards	✓			
Protrusion Hazards	✓			
Sharp Points and Edges	✓			
Pooling Water	✓			
<b>MAINTENANCE</b>				
Tilting and Frost Heave	✓			
Chain Wear	✓			
Tangled Chains	✓			
Cracked and Worn Swing Seats	✓			
Bearing Wear	✓			
Lubrication	✓			
Loose/worn/missing Fasteners	✓			
Wood Spliners/Cracking	✓			
Broken/Damaged or Missing Parts	✓			
Finish/Paint and Rust	✓			
<b>SITE</b>				
Fencing	✓			
Lighting	✓			
Signs	✓			
Furniture	✓			
Pathways	✓			
Pests/Insestations	✓			
Waste Bins	✓			
General Housekeeping	D	CLEAN UP	25/3/2018	C. Gilmore

<b>NOTES;</b>				
BROKEN BEER BOTTLE @ LARGE SLIDE - CLEANED AND TIDIED C. Gilmore				

PLEASE USE REVERSE OF SHEET FOR FURTHER INFORMATION/DETAILS